FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 16/16/85	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 364	DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	NAME OF CONTRACTOR Holder Bours
WAS ATTACHED TO MAIN	77,112 21 35,171,171
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
Jandil Sararo	FILED AT ENGINEER'S OFFICE
SIGNED THAT Inspector for City	FILED AT ENGINEERS OF TIME
REMARKS NO REPAIR	

√² 9643

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

	MASSILLON, OH!	o, Oct. 16
RECEIVED OF GARY	Holderbau	FEE OF \$ 2
FOR WHICH PERMISSION IS GRANTED	ST. George's	Church
TO TAPSANC	SEWER ON THE	EAST
of 364-1 at 2t 8, E.	AVE. ST. TYPE OF STREET	ASPHALT
THE PREMISES BEING LOT NO. 366	, но	use no. 3 6 44
WORK TO BE DONE IN ACCORDANCE WITH OF THE DEPARTMENT OF PUBLIC SERVICE.	ORDINANCE NO. 19.1971 DUL	Y PASSED BY THE CITY COUNCIL, AND
	, l- 1100 150	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.

2-20139