

Nº 9648

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED October 31, 1984

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 401

SIZE OF PIPE USED 6" ^{UP} DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


60 1/2' 9FT Deep

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR PIAS

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Karol Sasar
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

2 FT FROM CURB, REPAIR 2 FT SECTION OF PIPE

REPAIR

Nº 9648

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

Oct 31

RECEIVED OF

Plas Co. Remediating

FEE OF \$

25

FOR WHICH PERMISSION IS GRANTED

James P. Smith

TO-TAP

Sanitary

SEWER ON THE

South

OF

Sheri Ave NE

AVE.

ST. TYPE OF STREET

Sanitary

THE PREMISES BEING LOT NO.

11500

HOUSE NO.

401

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Plas

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**