1º 9656 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED Dec. 5, 1984	IF SO HOW AND LOCATION FROM GOES INTO Manhole
HOUSE NO. //60	·
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT GOES INTO MANHOLE 13FT Deep CURB LINE AND DEPTH GOES INTO MANHOLE 13FT Deep
WAS LATERAL AT CURB? 1/05	NAME OF CONTRACTOR Holderbaum
WAS ATTACHED TO MAIN	
SHOW BY DIAGRAM RELATION OF LATERAL	TO WALL OF BUILDING SERVED. 4PT IRON
SIGNED Wed Janara Inspector	GARAGE DOORS FACE IN PARTY 32 A ST THOMAS 1/2 FT THE 45° 6FT Deep FROM 45° TO 45° - 76FT FILED AT ENGINEER'S OFFICE
REMARKS	

√º 9656

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

, ***	MASSILLON, (оню, <i>Nov 30</i>
		FEE OF \$
		Alonin
the state of the s		14 (12)
THE PREMISES BEING LOT NO	14119	HOUSE NO
OF THE DEPARTMENT OF PUBLIC		DULY PASSED BY THE CITY COUNCIL, AND

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.