Nº 9664

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

	DATE INSPECTED FEBRUARY 1, 1985	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	· -
	HOUSE NO. 220/		
		DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	·
· 	WAS LATERAL AT CURB?		
	WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Se/F	
	SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	L OF BUILDING SERVED. K6'>)
	en de la companya de La companya de la co		
		26' 7' Deep	
•			
		1 +249 -> /50°	
	$\Omega I = 0$		
	SIGNED Handle Hanavior Inspector for City	FILED AT ENGINEER'S OFFICE	
	Inspector for City	FILED AT ENGINEER O OF TOLLEGE	
	REMARKS CEMENT (4) Floor	DRAINS	
	REMARKS 2 22 22 22 22 22 22 22 22 22 22 22 22		

Cut #\ Vº 9664

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

IERMIII IO IAI SEWER
MASSILLON, OHIO, Jan 3/
RECEIVED OF Malan Chavala FEE OF \$5.
FOR WHICH PERMISSION IS GRANTED TO CROWN
TO THE CILL AND SEWER ON THE SOUTH
OF DIAMAN (IN ME. TYPE OF STREET CREPT SPAL
THE PREMISES BEING LOT NO. 1,037 , HOUSE NO. 220/
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.