

✓ ✓
Nº 9667

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED MARCH 20, 1985

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1200

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

160'-7' Deep


WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR

PIAS

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Harold Sarnes
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Repair 26 FT of Lateral

Repair
N^o 9667

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *March 19*

RECEIVED OF *Plus Excavating* FEE OF \$ *2*

FOR WHICH PERMISSION IS GRANTED *Jim Plus*

TO TAP *Repair* SEWER ON THE *Last*

OF *1200 Miles SW* AVE. ST. TYPE OF STREET *asphalt*

THE PREMISES BEING LOT NO. *8966*, HOUSE NO. *1200*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Plus Inc*

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.