

✓
Nº 9668

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

MARCH 24, 1985

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

936

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED

4"

WAS LATERAL AT CURB?

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Richardson

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N →

45° MH 2FT DEEP
↓
Flow →

SIGNED

Knoll Sasano
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Took old wye out, and PUT - 45° and 2FT OF 4" inside MH

Repair

Nº 9668

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

March 21

RECEIVED OF

A. J. Quinn, Jr.

FEE OF \$ 2

FOR WHICH PERMISSION IS GRANTED

same

TO TAP

sewer

SEWER ON THE

same

OF

74th Street SW

AVE.

ST. TYPE OF STREET

blacktop

THE PREMISES BEING LOT NO.

3350

HOUSE NO.

936

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

A. J. Quinn, Jr.

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**