

Nº

9670

✓
✓
FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNEDDATE INSPECTED 6-5-85IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM231'HOUSE NO. 936

SIZE OF PIPE USED

6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB?

YES


WAS ATTACHED TO MAIN

YES

NAME OF CONTRACTOR

Jacob Gluck

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Bill Pappas
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

30° Bend at curb

Nº 9670

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, April 1

RECEIVED OF

JACOB GLICK

FEE OF \$ 25

FOR WHICH PERMISSION IS GRANTED

JACOB GLICK

TO TAP

SANITARY

SEWER ON THE

EAST

OF

CARNATION ST. NE

AVE.

ST. TYPE OF STREET

CITY SEAL

THE PREMISES BEING LOT NO.

14078

HOUSE NO.

936

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

JACOB GLICK

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**