

N^o


9673

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNEDDATE INSPECTED 4-18-85IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAMWye at 217HOUSE NO. 852SIZE OF PIPE USED 16"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH217 9' DeepWAS LATERAL AT CURB? yesWAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR

Schaer & Son

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

new account

Nº 9673

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, _____

RECEIVED OF _____ FEE OF \$ _____

FOR WHICH PERMISSION IS GRANTED CHAPMAN

TO TAP _____ SEWER ON THE _____

OF 15th St NW AVE.
ST. TYPE OF STREET _____

THE PREMISES BEING LOT NO. 7935, HOUSE NO. 852

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR _____

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**