

Nº 9682

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 6-25-85

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 106'

HOUSE NO. 1220

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 6' DEEP

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR Malavite

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED William Pappas
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS Put in y at main, connected by N.E. line

Tapping
N^o 9682

9 AM start.
OFFICE OF THE DIRECTOR OF PUBLIC SEW
PERMIT TO TAP SEWER

MASSILLON, OHIO, *June 21*

RECEIVED OF *Malavite Excavating*

FEE OF \$ *2*

FOR WHICH PERMISSION IS GRANTED *Same*

TO TAP *Sanitary*

SEWER ON THE *East North*

OF *Lincoln*

ST. TYPE OF STREET *Grande*

THE PREMISES BEING LOT NO. *9553*

HOUSE NO. *1220*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Malavite Excavating*

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**