

Nº 9692

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 8-5-85

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM —

HOUSE NO. 811

SIZE OF PIPE USED —


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH —

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR Colony

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



N 4

SIGNED Bill Pappas
Inspector for City

FILED AT ENGINEER'S OFFICE —

REMARKS Cut off

Cutoff

Ms. Shelley Davis

N^o 9692

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *Aug 5*

RECEIVED OF *Colony*

FEE OF \$ *5*

FOR WHICH PERMISSION IS GRANTED *same*

TO TAP *Sanitary*

SEWER ON THE *West*

OF *811 Walnut SE*

AVE.

ST. TYPE OF STREET *100 ft*

THE PREMISES BEING LOT NO. *10031*

HOUSE NO. *811*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Colony*

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**