

N^o

9693

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 9-18-85 IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 289'

HOUSE NO. 137

SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 189' 4'6" DEEP


WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES NAME OF CONTRACTOR Holderbaum

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

MAIN line 10' FROM Driveway?

18'
From
N.W. CORNER
of house.



N4

SIGNED

William P. Passer

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Repair

Nº 9693

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

Aug 13

RECEIVED OF

Gary Holderbaum

FEE OF \$ 2.50

FOR WHICH PERMISSION IS GRANTED

same

TO TAP

sanitary

SEWER ON THE

South

OF

Olman St. NE

AVE.

ST. TYPE OF STREET

asphalt

THE PREMISES BEING LOT NO.

9681

HOUSE NO.

137

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19,1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Holderbaum

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**

1-6423