

Nº 9707

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 1-7-86

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 510

SIZE OF PIPE USED 4"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.


19' FROM WEST LOT LINE
1-8' DEEP
186' FROM CURB

N 4

SIGNED

William Pappas

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Cuttop

N^o 9707

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *Jan. 6*

RECEIVED OF *City*

FEE OF \$ *3*

FOR WHICH PERMISSION IS GRANTED *same*

TO TAP *Sanitary*

SEWER ON THE *North*

OF *Lincoln Way E*

AVE.

ST. TYPE OF STREET *Asphalt*

THE PREMISES BEING LOT NO. *431*

HOUSE NO. *510*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *City*

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**