Nº 9708 ✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED /- 7-86	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 1203 SIZE OF PIPE USED 4"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS ATTACHED TO MAIN NO.	NAME OF CONTRACTOR Column	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
2'PREP	CLEVETAND AVES	
SIGNED William Papers Inspector for City	· · · · · · · · · · · · · · · · · · ·	
Rock house bokad	in to facet houses.	

*luto/6* Nº 9708

## OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

MASS	SSILLON, OHIO, AO
RECEIVED OF COLUMN	FEE OF \$-5
- FOR WHICH PERMISSION IS GRANTED	<u> 388</u>
TO TAP SEWER ON	ON THE MAICH
TO TAP SEWER ON AVE. AVE. ST. TYPE OF	F STREET aspluch
	, HOUSE NO
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1 OF THE DEPARTMENT OF PUBLIC SERVICE.	0.1971 DULY PASSED BY THE CITY COUNCIL, AND
NAME OF CONTRACTOR COLLO	<u></u>

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.