## Nº 9723 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

5 7 D1	
DATE INSPECTED 5-7-26	FIRST MANHOLE DOWN STREAM 30
HOUSE NO. 1725 AUBILAN	N.W.
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? YES	
WAS ATTACHED TO MAINX/= S	NAME OF CONTRACTOR SHETLER EXCAUNTING
SHOW BY DIAGRAM RELATION OF LATERAL TO W	ALL OF BUILDING SERVED.
N.E.	ER House
	K15 - 1 1
and the second s	a LE CURB NORTH
7/H 30	7 DEEP.
· ·	6" PIPE
$\Omega$ . $\Lambda$	
SIGNED Gand m. ack	EM FILED AT ENGINEER'S OFFICE
Inspector for Cit	
REMARKS	

1///////\ № 9723

## OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

	MASSILLON, OHIO, ///////
RECEIVED OF	11111 16 (12) FEE OF \$ 2
FOR WHICH PERMISSION IS GRANTED ()///)	11 <u>E</u>
TO TAP	SEWER ON THE
OF 1 CHL 1 CH ST.	
THE PREMISES BEING LOT NO. 14/33	Salar Control of the
OF THE DEPARTMENT OF PUBLIC SERVICE.  NAME OF CONTRACTOR	Commission of the Commission o
NAME OF CONTRACTOR	<u> </u>

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.