Nº ∫ 9731

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED | IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM |
|--|---|
| HOUSE NO. 23/12 | DISTANCE FROM FIRST MANHOLE |
| SIZE OF PIPE USED | DOWN STREAM TO DITCH AT CURB LINE AND DEPTH |
| WAS LATERAL AT CURB? TE 5 | |
| WAS ATTACHED TO MAIN 455 | NAME OF CONTRACTOR Oakes Const |
| SHOW BY DIAGRAM RELATION OF LATERAL TO WALL, OF BUILDING SERVED. | |
| 45° 24' 8'6" | Drep AT COMNection |
| | |
| SIGNED William Passas Jispector for City | FILED AT ENGINEER'S OFFICE |
| REMARKS Clean Out on East side of building | |
| | \checkmark |

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR (JULIER) (17/107

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.