Nº ∫ 9743

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED | IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM |
|---|---|
| HOUSE NO | |
| SIZE OF PIPE USED | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH |
| WAS LATERAL AT CURB? | |
| WAS ATTACHED TO MAINSHOW BY DIAGRAM RELATION OF LATERAL TO WALL | NAME OF CONTRACTOR |

SIGNED MANUAL JASE AND INSPECTOR FOR City

_ FILED AT ENGINEER'S OFFICE__

EMARKS NO LNSpecton 2-12-87

OFFICE OF THE DIRECTOR OF PUBLIC SER

| Nº 9743 | PERMIT TO TA | AP SEWER |
|--------------------------------------|--------------------------------|-------------------|
| Sohio | MASSILLON, OHIO, | <u> Jep. 30 .</u> |
| RECEIVED OF HY | Contractor | FEE OF \$_2 |
| OR WHICH PERMISSION IS GRANTED | <u> Dance</u> | |
| O TAP SULLI TULL | SEWER ON THE | 11 th |
| OTAP SUICH TOLY | 7/1 SVE. ST. TYPE OF STREET 11 | owhilt |
| HE PREMISES BEING LOT NO. | 1447/8 , HOUSE NO. | 27// |
| YORK TO BE DONE IN ACCORDANCE WITH C | | |

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.