
## Nº 9760 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-19-87 HOUSE NO. /68	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH
WAS LATERAL AT CURB? YE 5	
WAS ATTACHED TO MAIN 72 5 SHOW BY DIAGRAM RELATION OF LATERAL TO WA	NAME OF CONTRACTOR B+B Wredsing  LL OF BUILDING SERVED.



SIGNED Villian	annes	FILED A	T ENGINEER'S	OFFICE
	// Inspector for City	. •		

REMARKS \_\_\_\_\_

Nº 9760

## OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

MASSILLON, OHIO, Solv 18
RECEIVED OF LOG WILLIAM FEE OF \$
FOR WHICH PERMISSION IS GRANTED 13/11/0
TO TAP SEWER ON THE
OF LUCU AVE. ST. TYPE OF STREET
THE PREMISES BEING LOT NO
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
NAME OF CONTRACTOR 3 + B WILL PUTE.
NAME OF CONTRACTOR / / Contractor / / / / / / / / / / / / / / / / / / /

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.