Nº 9772

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-26-87	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO. 2315			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT		
V	CURB LINE AND DEPTH		
WAS LATERAL AT CURB? YES	0 1		
WAS ATTACHED TO MAIN 4/25	NAME OF CONTRACTOR Lasure Const.		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.			
8 OR P T PET CURB			
SIGNED William Papaces	FILED AT ENGINEER'S OFFICE		
REMARKS			

100

Called Buit 3/26,00

1:00-1:00

Nº 9772

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

-	MASSILLON, OHIO,	3/26
RECEIVED OF	Court.	FEE OF \$
FOR WHICH PERMISSION IS GRANTED		
то тар	EWER ON THE	<u></u>
OF AVE. ST. 1	TYPE OF STREET	
THE PREMISES BEING LOT NO. 14103		
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE		
OF THE DEPARTMENT OF PUBLIC SERVICE.		
NAME OF CONTRACTOR		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.