

N^o

9775

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNEDDATE INSPECTED 4-13-87IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM69'HOUSE NO. 1246DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTHSIZE OF PIPE USED —WAS LATERAL AT CURB? —WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR

Beaver Const.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



N 4

SIGNED

William Pappas

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Cutoff

Cuttoff
N^o 9775

OFFICE OF THE DIRECTOR OF PUBLIC SER
PERMIT TO TAP SEWER

MASSILLON, OHIO, *May 27*

RECEIVED OF *Beaver Etc*

FEE OF \$ *5*

FOR WHICH PERMISSION IS GRANTED *same*

TO TAP *Cuttoff*

SEWER ON THE *N*

OF *Lincoln*

AVE.

ST. TYPE OF STREET *and*

THE PREMISES BEING LOT NO. *9548*

HOUSE NO. *1246*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Beaver Etc*

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**