1/20c

Nº 9782

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR

cancel - I transfer to #98/1

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM			
HOUSE NO				
	DISTANCE FROM FIRST MANHOLE			
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT			
	CURB LINE AND DEPTH			
WAS LATERAL AT CURB?				
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR			
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.				
SHOW BY BINGHAM REENHOUGH OF ENTERNE TO WAS	3 . 2 3.222 22			

see permit # 9811-

SIGNED______ FILED AT ENGINEER'S OFFICE______

REMARK

rs.

√º 9782

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

	MAS	SSILLON, OHIO,	<u> 181716 26</u>	
DECEIVED OF				FEE OF \$
RECEIVED OF	EDWINT	SMUM	n Marianting (B) (1972) and a till staking all processings in page 1988 days from the	_{and} see of t
TO TAP	SEWER	ON THE	, <u>)</u> ,	
OF FALLEN DAIL N.F.	AVE.	F STREET/	() ³	
THE PREMISES BEING LOT NO.	78	, HOUSE N	10. <u>2336</u>	<u>}</u>
WORK TO BE DONE IN ACCORDANCE WITH OF OF THE DEPARTMENT OF PUBLIC SERVICE.		9.19 71 DULY FA	SSED BY THE CIT	COUNCIL, AND
NAME OF CONTRACTOR FREE PARK	1->0		-	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.