N^{2} 9799 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

	DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
	HOUSE NO. 431	THE PART OF THE PA
	SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
	WAS LATERAL AT CURB? YES	•
	. مسلم	NAME OF CONTRACTOR
	SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	OF BUILDING SERVED.
	The said of the sa	N. A
٠	DEAP.	2
	SIGNED Willia Carries	FILED AT ENGINEER'S OFFICE
	Inspector for City	
	REMARKS Cetall	

OFFICE OF THE DIRECTOR OF PUBLIC SEE Nº 9799 PERMIT TO TAP SEWER

	MASSILLON, OHIO, JULY
per.	RECEIVED OF AMERICAN LECTION FEE OF \$ 5.
-	FOR WHICH PERMISSION IS GRANTED AMERICAN LEGION
-	TO SUT OFF SONITARY SEWER ON THE SOUTH
	OF LINCOLIN WAY EAST ST. TYPE OF STREET HARD SURFA
	THE PREMISES BEING LOT NO. 230
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.