

✓  
✓  
Nº 9811

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED**

DATE INSPECTED 9-18-87

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM

HOUSE NO. 2336

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR Trank's

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



N-1

SIGNED William P. Rogers  
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº *TAP* 9811

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE  
PERMIT TO TAP SEWER

MASSILLON, OHIO, *Sept '8*

RECEIVED OF *Franks*

FEE OF \$ *2*

FOR WHICH PERMISSION IS GRANTED *Home*

TO TAP *Sanitary*

SEWER ON THE *N*

OF *Julien Ave*

AVE.

ST. TYPE OF STREET

THE PREMISES BEING LOT NO. *14178*

HOUSE NO. *2336*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND  
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *James K. Franks*

**Note: This permit covers work outside of building only. Any work  
walls of building is subject to Massillon Board of Health Regulations.**