

✓
✓
Nº 9815

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 9-29-87

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

LINE GOES INTO MH BETWEEN 649-645

HOUSE NO. 707

SIZE OF PIPE USED

6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB?

No


WAS ATTACHED TO MAIN

No

NAME OF CONTRACTOR

H+W cont.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

William Pappas
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 9815

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

Addition

MASSILLON, OHIO,

Apr 29

RECEIVED OF

Hans Carl

FEE OF \$

25

FOR WHICH PERMISSION IS GRANTED

Same

TO TAP

Sanitary

SEWER ON THE

South

OF

1-10 W

AVE.

ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

467

HOUSE NO.

767

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19,1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

H & W Ponton

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**