

Nº 9817

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-8-87

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 901

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR

Schaer & Son

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

William Passus
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

6\"/>

Nº

9817

ADDITION

Repair

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

Oct 7

RECEIVED OF

Robert Schaefer

FEE OF \$ *2*

FOR WHICH PERMISSION IS GRANTED

Same

TO TAP

Sanitary

SEWER ON THE

South

OF

Card 77 E

AVE.

ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

11574

HOUSE NO.

901

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Schaefer & Son

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.