Nº 09900

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 17-2-88	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 130
HOUSE NO. 815	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT
· · · · · · · · · · · · · · · · · · ·	CURB LINE AND DEPTH
WAS LATERAL AT CURB?	. 01 /
WAS ATTACHED TO MAIN 1/ES THE WH	NAME OF CONTRACTOR 98 olderbaum
	OW. I PEDI
6	BERTHAD SW.
	BERTHROLSW.
	NA
	367
Iron	city Sash + Door

Inspector for City

vaccion for 11124 10/31

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

and the second s	MASSILLON, OHIO,	<u> </u>		
RECEIVED OF 100	Holdedal	(11 ha	FEE OF \$	5Q.4
	War on Ci			
TO TAP STEEL SECTION	SEWER ON THE	Sict	1	SIDE
or Obecler Sc	AVE.			SIDE
	Hous	E NO.	15	,
WORK TO BE DONE IN ACCORDANCE WITH BE				ON.
NO. OF UNITS OWNER	LCALL CODIFIED ORD	Laul s	7016c	
NAME OF CONTRACTOR	Control of the Contro		1	<u> </u>

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.