Nº 09913 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	FIRST MANHOLE DOWN STREAM
HOUSE NO. 821-823	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CORBI	
WAS ATTACHED TO MAIN 4ES	NAME OF CONTRACTOR Desuce
7' 6'0669	N L CURBINE
$\omega \cup HeA$	Place 11 8

SIGNED Bill Papas

09913

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

•	MASSILLON, OHIO,	140 22	19
RECEIVED OF	<u> Ell</u>	FFF OF \$	Car Colum
FOR WHICH PERMISSION IS GRANTED			
TO TAP LACE PLACE	SEWER ON THE		SIDE
THE PREMISES BEING LOT NO.		NO. 821-823	
WORK TO BE DONE IN ACCORDANCE WITH SECTION	ON 29 OF THE CODIFIED ORDIN	NANCES OF THE CITY OF MASSI	LLON.
NO. OF UNITS OWNER	Marin Colors	Marga.	
NAME OF CONTRACTOR	<u> </u>		(

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.