Nº 09923

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 2:22-89 HOUSE NO. 2728	IF SO HOW AND LOCATION FROM 88
SIZE OF PIPE USED 6" WAS LATERAL AT CURB? 155	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS ATTACHED TO MAIN 18	NAME OF CONTRACTOR MAlivite Equ.
	12/2 - 11'DEEP 12/2 - 11'DEEP 12/2 - 11'DEEP

GNED Sill of the Sill inspector for Cit

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

Nº 09923

	MASSILLON,	OHIO,	, 19_ <u></u>
RECEIVED OF	Progressian	FEE O	F \$
FOR WHICH PERMISSION IS GRANTED.			
то тар	•		
DF			
THE PREMISES BEING LOT NO	108 0	. HOUSE NO.	
WORK TO BE DONE IN ACCORDANCE V	WITH SECTION 29 OF THE CODIFIE	ED ORDINANCES OF THE CITY OF M	MASSILLON.
NO. OF UNITS OW	/NER Property	:	
NAME OF CONTRACTOR	<u> </u>		(

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.