

# STARK SOIL & WATER CONSERVATION DISTRICT

2650 RICHVILLE DR SE, SUITE 103, \* MASSILLON, OH 44646 \* (330) 830-7700  
FAX: (330) 830-7731

## SITE INSPECTION REPORT

Report Mailed: ☒

### \*\*\*\* Notice of Non-compliance \*\*\*\*

**Report Date:** March 27, 2008

**Inspection Date:** 3/26/2008

**Site Name:** Menard Inc. Development

**Inspected By:** J Berbari

**Owner:** Menard Inc.

**Township/City/Village:** Massillon City

**Address:** 4777 Menard Drive

**Site NPDES Number:** 3GC03459\*AG  
(If Applicable)

Eau Claire, WI 54703

**Phone:** (715) 876-2308

**Fax:**

**Contact:** Jim Carlson

### Site Conditions and Compliance Activities Required

This office performed a compliance inspection for storm water best management practices at the above-mentioned site.

#### NON-COMPLIANCE NOTICE

This site is now considered a non-compliance site for the following reason (s):

\*\*\* The culvert installation was not completed. Dirt was piled on top of the pipe where it can easily reach the stream (see pictures). The small sections of silt fence are not adequate erosion or sediment control.

This site will be inspected weekly until compliance is met. Each non-compliance inspection is subject to an additional inspection fee at a rate of \$45.00/hour.

#### Next Inspection

The next site inspection will be in one week.

#### Comments:

If you have any questions concerning this inspection, please contact the office at 330-830-7700 ext. 127.

**cc:** Keith Dylewski, Massillon City Engineer