FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Nº 1923

Signed Inspector for	Filed at Engineer's Office
while filler with manufacture and the	Euru
	3 7 feet deep
Show by diagram relation of lateral	o wall of building served.
Was attached to main.	
Was lateral at curb?	Name of Contractor Qu Monstim
Size of pipe used (And)	down stream to ditch at curb line and depth
House No. 616, 548	first manhole down stream Distance from first manhole
Date Inspected AMB	If so how and location from first manhole down stream.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

	Massillon, O.,	0 1943
Received of		fee of \$
for which permission i	s granted Units RY	Ve man and the second
	galastan diaka di kabupatèn kacamatan di kabupatèn	() by the second
to tap	sewer, on the	side
		2496
of		ses being Lot. No.
548	St.	11 Th
House No.	Work to be done in accordance with	Ordinance No. 2323, duly passed
by the City Council, ar	nd Rules of the Department of Public Serv	ice.
	(+ 1 + +	
Name of Contractor	Undown Warling	