WANTS	INSPECTUR	1100	OCLUC

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

N.	1940	WILL KEICKNED	and the same of
	pected A4421	If so how and location from	
House No.	. Let 39 900	first manhole down stream Distance from first manhole	
	pe used H mol	down stream to ditch at 81 ful from South cuts dine of de	Le St. 5 foot old
Was later	al at curb? 44	Charatte	
Was attac	ched to main	Name of Contractor Chas. Strut	
Show by	diagram relation of la	ateral to wall of building served.	100
		2 fut from Jouth yart Corner Main Building	
		yart Corner Main	The state of the s
	그리다는 경험에 가는 이 경우는 보이다. 	Building	
		6-8 Weeks even.	
	age, medical policy in the		
Signed	Um. L	Third Filed at Engineer's Office 1726	125
	Inspecto	or for City	•

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 1940

PERMIT TO TAP SEWER

				/	
		Massillon,	o.,	eg 211	19 ⁻² ა ˙
				\mathcal{U}	
	00	Strond	na na salah sa Kanadaran	· · · · · · · · · · · · · · · · · · ·	U
Received of .	CK C-	many en	leave.	fee of \$ 2 4	
			1		
or wh <mark>ich permissi</mark> c	on is granted	- Nete	Maria	<u> </u>	
. 2		in <mark>i 13 l</mark> ahya ing t	0		
o tap	was any	sewer, on the	horth	averde	side
f Third	1 Lake				
E Pro Billion	7-1114	Stee e done in accordance	premises being	7455	#
Iouse No.		e done in accordance	with Ordinance	e No. 2323, duly	y passed
y the City Council	l, and Rules of the	Department of Publi	c Service.	**************************************	
Vame of Contracto	r clash	trend			