

N^o 1943

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

5-7

Date Inspected Aug. 24, 1925

If so how and location from
first manhole down stream

House No. 1744 1219

Size of pipe used 6 inch

Distance from first manhole
down stream to ditch at
curb line and depth

30 feet from Man Hole North. 7-6. Deep.

Was lateral at curb? yes.


Name of Contractor

James V. Brunker

Was attached to main yes.

Show by diagram relation of lateral to wall of building served.

20-4 inches from
North corner the
Main Building
6-6. Deep.



Signed

Wm. Nesbitt
Inspector for City

Filed at Engineer's Office

8/25/25

Remarks

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 1943

PERMIT TO TAP SEWER

Massillon, O., _____ 19____

Received of Jess Brunken fee of \$ _____

for which permission is granted Geo. Eberhardt

to tap sanitary sewer, on the west side

of N. Mill Ave., the premises being Lot. No. 1219
1711 1st ST NE St. 2693/332

House No. 1711 Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor Deshon & Brunken