

✓
D

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 1947

Date Inspected Aug. 24, 1925

If so how and location from
first manhole down stream

House No. 418 254

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 6 inch

9-9 from Main Hole South 5 feet deep

Was lateral at curb? yes


Name of Contractor

Was attached to main yes

Julius Wittman

Show by diagram relation of lateral to wall of building served.

24-2 inches from
South West corner
pillar the porch.
3-6. deep.



Signed

Wm. Oleshan

Inspector for City

Filed at Engineer's Office

8/25/25

Remarks

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 1947

PERMIT TO TAP SEWER

Massillon, O., 8/25/25 1925

Received of Julius Witman fee of \$ 2.00

for which permission is granted J. Witman

to tap San. sewer, on the East side

of Independence Ave., the premises being Lot. No. 21321
254 St. 3458

House No. 418 Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor J. Witman