## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Nº 1956

Date Inspected 10-1925	If so how and location from first manhole down stream
House No Let 1230	Distance from first manhole
Size of pipe used 6 inch	down stream to ditch at curb line and depth
Was lateral at curb?	Alin Wither 20
Was attached to main 175.	Name of Contractor
	819 Wyoming
Show by diagram relation of lateral to	wall of building served
A Williams	7
12	SILL 8-0"
FOSLYN	\$6. 512. 8-0"
I ROOF	7 20' - FRE 6 47 × 29 ->
B"LINE	CAPPED TO FMANHOLE.
	POSE ST
N. A.	SEXE STUBY
	INVERT BUILT IN MY.
Signed COUNTY AND STATE OF THE	Filed at Engineer's Office Sylv 14 1925
Inspector for Cit	
Remarks 8" STUB 4XT 1/84	ERT IN MH BUILT AS SHOWN.

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## **Nº** 1956

## PERMIT TO TAP SEWER

er en er	in a chaire was a same to be Massillon, O., -	Cing 31 A 1925
Received of	I With ann	fee of \$ 200
	ion is granted Charles Ou	reger of
A.	the control of the co	**************************************
to tap	sewer, on the	side
of	Wyoming Ave., the premi	ises being Lot. No 3 3 9
	St.	1230
House No. 819	Work to be done in accordance with	Ordinance No. 2323, duly passed
by the City Counc	ril, and Rules of the Department of Public Ser	vice.
Name of Contract	or 1 N ett an	