

✓

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 1961

3-50

Date Inspected Sept. 2, 1925

If so how and location from
first manhole down stream

House No. Lot 1214

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 6 inch

69 feet from Man Hole south 4-8 feet deep

Was lateral at curb? yes


Name of Contractor

Was attached to main yes

James Brundage & John Ashburn

Show by diagram relation of lateral to wall of building served.

11 feet from the Porch
West corner the Main
Building 6 feet deep



Signed

John Ashburn

Inspector for City

Filed at Engineer's Office

Sept 4th 1925

Remarks

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 1961

PERMIT TO TAP SEWER

Massillon, O.,

Sept. 2
1925

Received of

fee of \$

for which permission is granted

to tap

sewer, on the

side

of

1st ST NW

Ave., the premises being
St.

2576
1216

House No.

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor