

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 1966

LOT 0.6.126

Date Inspected Sept 8, 1925

If so how and location from first manhole down stream 107-6 from Main Ave. Sect. 3 - 0.126

House No. ~~2113~~ 1313

Distance from first manhole down stream to ditch at curb line and depth _____

Size of pipe used 4 inch

Was lateral at curb? yes


Name of Contractor James R. Bunker & John D. DeShore

Was attached to main yes

Show by diagram relation of lateral to wall of building served.

14-4 from North East
corner the Main
Building
6-6. Deep.

curb



Signed John D. DeShore
Inspector for City

Filed at Engineer's Office

SEP 9 1925

Remarks _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 1966

PERMIT TO TAP SEWER

Massillon, O., Sept 22 19

Received of John A. Woot fee of \$ 2.00

for which permission is granted

to tap Sanitary sewer, on the South side

of Winton Ave., the premises being Lot. No. 41
Lincoln Way W St. O.L. 126 9824

House No. 1313 Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor J. Brunker