

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 1968

LOT# 10087

Date Inspected Sept. 8, 1925

If so how and location from
first manhole down stream

House No. 1522 804

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 6 inch

60-10. from Main Hole east. 7-3. Depth.

Was lateral at curb? yes


Name of Contractor

Was attached to main yes.

A. Caplin

Show by diagram relation of lateral to wall of building served.

2.0 feet from South
West corner the
Main Building
8 feet deep.



Signed

Wm. Dechman

Inspector for City

Filed at Engineer's Office

SEP 9 1925

Remarks

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 1968

PERMIT TO TAP SEWER

Massillon, O.,

19

Received of

fee of \$

for which permission is granted

to tap

sewer, on the

side

of

Ave., the premises being Lot. No.
St.

House No.

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor