

✓

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 1980

Date Inspected Sept 23, 1925

If so how and location from
first manhole down stream _____

House No. Lot 98. 3851212

Distance from first manhole
down stream to ditch at
curb line and depth _____

Size of pipe used 4 inch

95 feet from Man Hole South. 5-6 Depth

Was lateral at curb? yes


Name of Contractor _____

Was attached to main _____

Jahir List

Show by diagram relation of lateral to wall of building served.

17-5. from South
gate corner from
Main Building
6-6. Depth



Signed _____

Mr. Dushon
Inspector for City

Filed at Engineer's Office _____

SEP 23 1925

Remarks _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 1980

PERMIT TO TAP SEWER

Massillon, O.,

Sept 21st 1935

Received of

fee of \$

for which permission is granted

to tap

sewer, on the

side

of

Ave., the premises being Lot. No.

House No.

857

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor