

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

4
39 ✓

Nº 1996

Date Inspected Oct 5, 1925

If so how and location from first manhole down stream 103-61st Ave. N. E. 1/2 Sec. 10, T. 9 N., R. 10 E.

House No. Lat. 103-61st Ave. N. E. 1/2 Sec. 10, T. 9 N., R. 10 E.

Distance from first manhole down stream to ditch at curb line and depth 9-0' Ditch

Size of pipe used 6 inch


Was lateral at curb? _____

Name of Contractor John. Bunker & John. Desbrow

Was attached to main yes

Show by diagram relation of lateral to wall of building served.

6-8, from South West corner from Main Building 5-6' deep



Signed John. Desbrow
Inspector for City

Filed at Engineer's Office OCT 6 1925

Remarks _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 1996

PERMIT TO TAP SEWER

Massillon, O.,

Oct 2

1925

Received of

Brunker & Hesdon

fee of \$

\$ 2.00

for which permission is granted

Carl Franz

to tap

Sanitary

sewer, on the

West

side

of

Hostetter Ch

Ave., the premises being Lot. No.

3004

St.

House No.

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor

Brunker & Hesdon