## Nº 2034

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Date Inspected 42 18.1925	If so how and location from first manhole down stream
House No. 1311 Size of pipe used 6 inch	Distance from first manhole down stream to ditch at curb line and depth 140-0 from Many Wole Path 7-0 de
Was lateral at curb?	Name of Contractor Jesus Brunker & John Washow
Was attached to main.  Show by diagram relation of lateral to	wall of building served.
3-2. from Now.	reli fillar Jewel
6-6. h	Delp:
Signed An Inspector for Cit	Filed at Engineer's Office
Remarks	

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## Nº 2034 PERMIT TO TAP SEWER

	Massillon, O.,		19
Received of	many distance and the state of	fee of \$2	4
or which permission is granted	1 2 1	- Jungan	
or which permission is granted			
to tap Jailang	sewer, on the	wish.	side
of Heavy	Ave., the premises	being Lot. No. 🕏 🍮	38
House No. 1311 Work to be done	e in accordance with O	rdinance No. 2323, du	ily pa
by the City Council, and Rules of the Depar	tment of Public Service	e.	
Name of Contractor			