

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

N^o 2038

✓
67

Date Inspected Oct. 31, 1925

If so how and location from
first manhole down stream _____

House No. 1141

Distance from first manhole
down stream to ditch at
curb line and depth 12 ft. - 2 ft. from Man. Hole to 5-0. deep

Size of pipe used 6 inch


Was lateral at curb? yes

Name of Contractor Chas. Street

Was attached to main _____

Show by diagram relation of lateral to wall of building served.

2-6 ft. from North West
corner. The porch
Pillar
5-0. Deep.



Signed _____

Inspector for City

Filed at Engineer's Office

NOV 2 1925

Remarks _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2038

PERMIT TO TAP SEWER

Massillon, O.,

1925

Received of

fee of \$

for which permission is granted

to tap

sewer, on the

side

of

Ave., the premises being Lot. No. 2125
St. 3449

House No. 1141

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor