Nº 2051

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Date Inspected 19 19 19 22	If so how and location from first manhole down stream				
House No. 4 24 224 Size of pipe used 6 MA	Distance from first manhole down stream to ditch at curb line and depth				
Was lateral at curb?	Name of Contractor Man Fine Service				
Show by diagram relation of lateral to	wall of building served.				
3-6. Deep the	he gode & Same				
Signed Inspector for Cit	File at Engineer's Office	0V2 6 1925			
Domanto					

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2051 PERMIT TO TAP SEWER

*	**************************************		Massillon, O.,	11/9	19-
	Received of	Jm Ji	isher	fee of \$	200
or v	vhich permissio	n is granted	a Strang	ls.	
o ta	p	to	sewer, on the	11802	oid.
of	Bu	che J 15th S'	I SW Ave., the premise St.	es being Lot. No.	2422 4265
	se No. 319		ne in accordance with (

by the City Council, and Rules of the Department of Public Service.

Name of Contractor John History