

✓

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 2060

Date Inspected Dec. 20, 1925

House No. Lat. No. 881

Size of pipe used 4 inch

Was lateral at curb? yes

Was attached to main _____


Show by diagram relation of lateral to wall of building served.

If so how and location from
first manhole down stream _____

Distance from first manhole
down stream to ditch at
curb line and depth 25' 5" - 6' from Man Hole Lately. 5' - 6" Deep

Name of Contractor Joe Brunken & John Deaton

3-7' from south east
corner the porch.
6-0" Deep.



Signed John Deaton
Inspector for City

Filed at Engineer's Office

NOV 23 1925

Remarks _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2060

PERMIT TO TAP SEWER

Massillon, O., Nov 11th 1922

Received of Brunner-Deshon fee of \$ 2⁰⁰

for which permission is granted B. J. Miller

to tap sanitary sewer, on the west side

of Danville Ave., the premises being Lot. No. 821
881 St.

House No. Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor Brunner-Deshon