


✓

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 2071

Date Inspected Nov 25-1925 If so how and location from
House No. 1119 first manhole down stream _____
Size of pipe used 6" Distance from first manhole
down stream to ditch at
curb line and depth _____
Was lateral at curb? NO
Was attached to main yes Name of Contractor Bunker. Peshon
Show by diagram relation of lateral to wall of building served.



Signed Clark Elmer Filed at Engineer's Office 11-27-25
Inspector for City
Remarks Lateral back 4 ft from curb in St.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2071

PERMIT TO TAP SEWER

Massillon, O., Mar 24th 1928

Received of Brunken - Dicks fee of \$ 2.00

for which permission is granted Peeler Iron & Steel Co.

to tap sanitary sewer, on the South side

of Oak Ave., the premises being Lot. No. Pl 969
St.

House No. 1119. Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor Brunken - Dicks