

N<sup>o</sup> 2087

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

Date Inspected 12/16/25

If so how and location from first manhole down stream \_\_\_\_\_

House No. 1012

Distance from first manhole down stream to ditch at curb line and depth \_\_\_\_\_

Size of pipe used 6"


7' deep  
159' from E.P.L. Hight

Was lateral at curb? yes

Name of Contractor J. Brumber

Was attached to main \_\_\_\_\_

Show by diagram relation of lateral to wall of building served.



Signed B. Jones  
Inspector for City

Filed at Engineer's Office 12/16/25

Remarks See Letter (filed under Brumber)

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2087

PERMIT TO TAP SEWER

Massillon, O., Dec 14th 1915

Received of Jess Brumby fee of \$ 2.00

for which permission is granted Crown

to tap Sanitary sewer, on the north side

of Hellman Ave., the premises being Lot. No. 529  
St. 1547

House No. 1016. Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor J Brumby