

✓

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 2091

Date Inspected 12/16/25

If so how and location from
first manhole down stream _____

House No. _____

Distance from first manhole
down stream to ditch at
curb line and depth _____

Size of pipe used 6" ^{4" inside} outside


7' below sidewalk
24' from E Waverley & Pole found

Was lateral at curb? at Prop. Line

Name of Contractor C. Strand

Was attached to main ✓

Show by diagram relation of lateral to wall of building served.



Signed _____

Inspector for City

Filed at Engineer's Office

12/16/25

Remarks _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 2091

PERMIT TO TAP SEWER

Massillon, O., Dec 16th 1911

Received of Chas. Starnes fee of \$ 2.00

for which permission is granted Thomas Bond

to tap Samsbury sewer, on the north side

of The Detroit Ave., the premises being Lot. No. 2261
St. 2262

House No. Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor J. H. Starnes

Inspector
1:00 o'clock

N.E. Cor
Ratch &
Wordley