

✓

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 2094

3-30

Date Inspected Jan. 7 - 1925

If so how and location from
first manhole down stream

House No. Lot 2308

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 6"


Was lateral at curb? yes

Name of Contractor

Was attached to main yes

Chas. Stroud

Show by diagram relation of lateral to wall of building served.



Signed

Clark Elser
Inspector for City

Filed at Engineer's Office

JAN 8 - 1925

Remarks

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2094

PERMIT TO TAP SEWER

Inspector ordered
2 P.M.

Massillon, O.,

July 7 1926

Received of

fee of \$

for which permission is granted

to tap

sewer, on the

side

of

Ave., the premises being Lot. No.

House No. 824

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor