# FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

#### Nº 2101

FEB2 4 1926	
Date Inspected 2, 1926	If so how and location from first manhole down stream 32' by tapping main.
House No	Distance from first manhole
Size of pipe used 6"	down stream to ditch at curb line and depth 37 - 2 Deep
Was lateral at curb? 200	(V) Strand
Was attached to main yes	Name of Contractor Mus
Show by diagram relation of lateral to	wall of building served.
	and the second of the second o
	18.40, 5.40, 4.40
	18.74.07
. The second of the second se	Ca. in the second secon
	32'0
	72 To Y conn.
Signed J. H. Wale.	FEB 2 4 192b
Inspector for City	
Remarks 18 Jull, app	žioz.

#### OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

### **Nº** 2101

## PERMIT TO TAP SEWER

	Ma	issilion, O.,		19
Received of	Ang H	4.	fee of \$	*
for which permission is grant	ed	444	***************************************	
to tap	sewer, o	on the	onto the	side
of his	Av	e., the premises beir	g Lot. No. P.11	37/
House No. 73/4 . W	York to be done in acco	ordance with Ordina	nce No. 2323, duly	pa'
by the City Council, and Rule	es of the Department of	of Public Service.		
Name of Contractor			And the second s	

FFB241926