## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Date Inspected MAR 121926	
House No. 26/5	If so how and location from first manhole down stream  Distance from first manhole
Size of pipe used	down stream to ditch at  curb line and depth
Was lateral at curb? 7	Name of Contractor L.E. Limbel
Was attached to main	Name of Contractor
Show by diagram relation of lateral t	to wall of building served.
	weght 25'
Signed J. H. Malu	Filed at Engineer's Office MAR 1 2 1926
Remarks Very little	full- sever installed in busement

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## **Nº** 2106

## PERMIT TO TAP SEWER

Received of	m. E.		ssillon, O.,	fee of \$	2 0 0
	ion is granted		and		
to tap	milan		on the	south	side
of U.I	remel	Av	e., the premises	being Lot. No.	3872

by the City Council, and Rules of the Department of Public Service.