FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

No	ด	135			
TA	æ	TOO)	2	Lann
			ΛDR	1 1	1970

ing the company of th	 Message in the control of the control	
Date Inspected	If so how and location from first manhole down stream	
House No. Mew 1025	Distance from first manhole	
Size of pipe used 6"	down stream to ditch at curb line and depth	
Was lateral at curb? 4.5. Was attached to main.	Name of Contractor Rhua I knowled	_
Show by diagram relation of lateral to	wall of building served.	
	Rotch st 70 634	
Signed J. II Make	Filed at Engineer's Office APR 1 7 1926	_
Inspector for Ci	ty	_

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2135

PERMIT TO TAP SEWER

	Massillon, O.,	april 16 4	19
Received of Chas. It	La song power day	fee of \$2	24
for which permission is granted aff	out the	Lylin	
to tap sandany se		South	side
of Roth		nises being Lot. No. 2	64
1025	St.	3761	1
House No. Work to be done in	accordance with	n Ordinance No. 2323, d	uly passed
by the City Council, and Rules of the Departm	ent of Public Sei	rvice.	
Name of Contractor C Atrona		. West of the second of the se	