

Nº 2147

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

✓
10
28

Date Inspected April 29th

House No. 821 538

Size of pipe used 6 in

Was lateral at curb? _____


Was attached to main _____

Show by diagram relation of lateral to wall of building served.

If so how and location from
first manhole down stream _____

Distance from first manhole
down stream to ditch at
curb line and depth _____

Name of Contractor C. Sprou



Signed A. F. Boyd
Inspector for City

Filed at Engineer's Office

APR 30 1926

Remarks Main over in alley south of house

~~No Record~~

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 2147

PERMIT TO TAP SEWER

Massillon, O.,

Apr 27 19

Received of

Chas Stroup

fee of \$

2.00

for which permission is granted

John Pet

to tap

San

sewer, on the

South

of

Babb

Ave., the premises being Lot. No. 71
St. West Park

side

5576-75

House No. 821 538

Work to be done in accordance with Ordinance No. 2323, duly passed
by the City Council, and Rules of the Department of Public Service.

Name of Contractor

Stroup